2 L REG

Articles
From
Around
The World



A Learjet 55's cockpit voice recorder, likely non-functional for years, hampers investigation into a fatal Philadelphia crash.

Read here

After a near-collision in Chicago, the FAA intensifies scrutiny on general aviation and business jets to enhance safety.

Read here

FAA Tightens Small Plane Oversight

DC Mid-Air Collision Sparks Safety Concerns

Over 15,000 close calls preceded a fatal mid-air collision in DC, prompting urgent NTSB safety recommendations.

Read here

A fatigue fracture in the main rotor gearbox led to a fatal CHC Helikopter Service crash, urging design reassessments.

Read here



2 L REG





Recent incidents highlight growing concerns in aviation safety, from nearmisses to maintenance failures.
Understanding these risks is crucial for operators and regulators.

Read here

A pilot's death near Fife Airport resulted from water contamination in the fuel system, leading to engine power loss.

Read here



Business Jet Runway Overrun

A Cessna Citation jet overran the runway during landing due to wet conditions, highlighting the need for precise approach planning.

Read here

A Robinson R44 helicopter made an emergency landing after fuel exhaustion, emphasizing the importance of accurate fuel management.

Read here

Helicopter Fuel Management Error