



Medical Jet's Silent Recorder

A Learjet 55's cockpit voice recorder, likely non-functional for years, hampers investigation into a fatal Philadelphia crash.

[Read here](#)

After a near-collision in Chicago, the FAA intensifies scrutiny on general aviation and business jets to enhance safety.

[Read here](#)



FAA Tightens Small Plane Oversight

Over 15,000 close calls preceded a fatal mid-air collision in DC, prompting urgent NTSB safety recommendations.

[Read here](#)



DC Mid-Air Collision Sparks Safety Concerns

A fatigue fracture in the main rotor gearbox led to a fatal CHC Helikopter Service crash, urging design reassessments.

[Read here](#)



CHC Helikopter Gearbox Failure



Aviation Safety: Key Threats in 2025

Recent incidents highlight growing concerns in aviation safety, from near-misses to maintenance failures. Understanding these risks is crucial for operators and regulators.

[Read here](#)

A pilot's death near Fife Airport resulted from water contamination in the fuel system, leading to engine power loss.

[Read here](#)



Water in Fuel Causes Fatal Crash

A Cessna Citation jet overran the runway during landing due to wet conditions, highlighting the need for precise approach planning.

[Read here](#)



Business Jet Runway Overrun

A Robinson R44 helicopter made an emergency landing after fuel exhaustion, emphasizing the importance of accurate fuel management.

[Read here](#)



Helicopter Fuel Management Error