



Maintenance Ground Run

A TSB investigation found an AS350 entered an uncommanded rotation during maintenance ground runs, prompting new procedures and hazard assessments.

[Read here](#)

A JetBlue A321 reported striking a drone during approach to JFK, highlighting the growing threat of unauthorised drones around controlled airspace.

[Read here](#)

Drone Strike Investigation



RC Aircraft Near Miss

Hours after the JFK drone incident, a Bell 407 pilot narrowly avoided a large remote-controlled aircraft near New York airspace.

[Read here](#)

Investigators continue examining a fatal Citation Latitude accident after the crew reported mechanical problems during the final approach to land.

[Read here](#)

NetJets Final Approach



Pressurisation Events

The ATSB has opened an investigation after repeated Embraer 190 pressurisation events, examining crew response, maintenance and system reliability.

[Read here](#)

The ATSB is investigating an uncommanded descent involving an AW139, providing valuable lessons for helicopter operators and maintenance teams.

[Read here](#)

AW139 Descent Investigation



Smarter Turbulence Prediction

New technology is helping pilots predict turbulence more accurately, improving decision making, reducing injuries and making flight planning more efficient.

[Read here](#)

The UK CAA warns that over 100 million lithium batteries are packed incorrectly each year, increasing the risk of uncontrollable in-flight fires.

[Read here](#)

Battery Packing Warning